

**TOP SECRET****PRIORITY****OUT57038****T O P S E C R E T 022338Z**

1965 NOV 3 00 04Z

**PRIORITY** [REDACTED] 5779

25X1

**IDEALIST****ATTENTION:** [REDACTED]

25X1

**SUBJECT: EVALUATION OF MISSION C555C**

1. CAMERA B 8 WAS USED IN MISSION C555C FLOWN ON 19 OCTOBER 1965. PROCESSING WAS ACCOMPLISHED IN THE FIELD.

2. ORIGINAL NEGATIVE:

A. EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

3 NOV 1965

B. 9R SIDE: ROLLER CHATTER WAS NOTED THROUGHOUT THE MISSION ON THE INBOARD EDGE AND ON THE OUTBOARD EDGE FROM FRAME 1 TO 153. EDGE STATIC IS PRESENT ON BOTH EDGES. IN FRAMES 392, 393, 394 AND 396 THERE IS A LARGE AREA OF FOG EXTENDING INTO THE FORMAT FROM THE OUTBOARD EDGE. THERE IS MINOR FOG IN FRAME 351 THAT EXTENDS INTO THE FORMAT FROM THE OUTBOARD EDGE. IRREGULAR PLUS DENSITY STREAKS ARE FOUND IN VARIOUS PLACES IN THE FORMAT THROUGHOUT THE MISSION. A GOOD EXAMPLE MAY BE FOUND ON FRAME 1963. A MANUFACTURING SPLICE IS LOCATED IN FRAME 420.

C. 9L SIDE: EDGE STATIC AND MINOR EDGE FOG ARE PRESENT ON THE INBOARD EDGE. A ROW OF MINUS DENSITY DOTS 1 1/4" FROM THE INBOARD EDGE AND 1 1/2" APART WERE FIRST NOTED IN FRAME 133. THIS ROW OF DOTS GRADUALLY MOVE TOWARD THE CENTER OF FORMAT ENDING ON FRAME 714 2 1/4" FROM THE INBOARD EDGE. A BAND OF FOG APPROXIMATELY 1.4" WIDE IS PRESENT ON THE INBOARD EDGE OF FRAMES 1210 TO

ADMIN	
SEC BR	
P & DS	
CSD	
IPD	
PD	
PSD	
PSD-ICB	
TID	✓
IAD	
PAG	
DIAXX-4	
SPAD	
NSA-LO	
DIA-AP	

Advance copy  
Sanitized**TOP SECRET**

25X1

-2-

1215. A MANUFACTURING SPLICE IS LOCATED IN FRAME 195.

D. BOTH SIDES: HEAT SPLICES WERE NOTED FREQUENTLY THROUGHOUT THE MISSION. THE LAST TITLED FRAME OF THE MISSION IS 2199.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. PI SITABILITY IS GOOD.

B. PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 10 PERCENT OF THE MISSION.

T O P S E C R E T

--END OF MESSAGE--

1